



Accurate Heating and Air Conditioning

License # 1008392
10808 Foothill Blvd., 160-420
Rancho Cucamonga, CA 91730
Tel. 1 (888) 702-4822

CUSTOMER QUOTATION NO. 5229

[Redacted]

Created Date: 04/27/2020
Valid For: 30 Day(s)
Site: [Redacted]
Site Address: [Redacted] W Foothill Blvd
Upland CA 91786
Order No.:

Description

PM (5608) Found On's (WO-26765):

[Redacted] (04/27/2020) - Work Note

RTU 2 Carrier M: 48TJE012---52 1GA DOM:4/2000 S: 2200G30803

Unit was shut off prior to pm. Further troubleshooting needed. Siemens shows unit has not communicated since 5/16/2019 new indoor blower motor and blower pulley needed.

Accurate to check DC. Check and Rest DZC Controller. Hold reset for 10 sec. to reset. and test.

RTU 3 ICP M: PGE120HEA00A AA--- DOM:06/2008 S: G082420965

Unit shutting off due to high head pressure caused by seized outdoor blower motor CFM. New out door blower motor (cfm), fan blade, and corresponding capacitor needed.

RTU 5 ICP M:PGE120HEA00A AA--- DOM:06/2008 S: G082420967

Unit not running. further troubleshooting needed to perform pm. Siemens shows no comms since 7/30/2019.

RTU 2: Replace Indoor Blower Motor and Pulley, Troubleshooting Unit

RTU 2: Carrier M: 48TJE012---52 1GA DOM: 4/2000 S: 2200G30803

- RTU was shut off prior to pm. Further troubleshooting needed. Siemens shows unit has not communicated since 5/16/2019 new indoor blower motor and blower pulley needed.

Sub-Total ex Tax	[Redacted]
Tax	[Redacted]
Total inc Tax	\$1,888.00

RTU 3: Replace CFM, Blade and Cap

RTU 3: ICP M: PGE120HEA00A AA--- DOM:06/2008 S: G082420965

- Unit shutting off due to high head pressure caused by seized out door blower motor. New out door blower motor (cfm), fan blade, and corresponding capacitor needed. gas shut off to unit further troubleshooting needed to test heating ops.



Accurate Heating and Air Conditioning

License # 1008392
10808 Foothill Blvd., 160-420
Rancho Cucamonga, CA 91730
Tel. 1 (888) 702-4822

CUSTOMER QUOTATION NO. 5229

RTU 3: Replace CFM, Blade and Cap

Sub-Total ex Tax	██████████
Tax	\$50.78
Total inc Tax	██████████

RTU 5: Troubleshooting Comms

RTU 5: ICP M:PGE120HEA00A AA--- DOM:06/2008 S: G082420967

- RTU not running. further troubleshooting needed to perform pm. Siemens shows no coms since 7/30/2019.

Sub-Total ex Tax	██████████
Tax	██████████
Total inc Tax	\$170.00